

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Acura	Models with cruise control	>9/89	4904	
Acura	Models with cruise control (except Vigor) Integra	9/89>	4914	
Acura	Models without cruise control	>9/89	4903	
Acura	Models without cruise control	9/89>	4905	*4911 works better on the 94-02 Intergras
Acura	Vigor	All	4909	
Acura	Vigor	All	4913	
Acura	RSX	All	N/A	No Application.
Acura	NSX	All	4916	
Alfa Romeo	164	86-89	1014	
Alfa Romeo	164	90>	1017	
Alfa Romeo	Alfetta, Alfetta GT	All	0069	
Alfa Romeo	GTV-6	All	1009	
Alfa Romeo	Milano	86>	1011	
Alfa Romeo	Spider Veloce, Graduate	90>	0069	
Audi	100/200, 200 Quattro	88-94	2507	
Audi	4000 Quattro	84-87	8010	
Audi	4000, 4000S, 4000 5+5	79>	8010	
Audi	5000 Quattro Turbo	85-91	2507	
Audi	5000, 5000 Turbo	6/83	2507	
Audi	80 Quattro	88>	8013	08.26.05 Discontinued NLA
Audi	80/90, except Quattro, 90 Airbag	88-89	2507	
Audi	90 Quattro, 20 valve Quattro coupe	88-89	2507	
Audi	A4	98>	8015	07/05/05 - will not work on 97 cars
Audi	A6	97-99	8015	
Audi	A8	97-03	8015	
Audi	Coupe, Coupe GT	All	8010	
Audi	Fox	79	8010	
Audi	Quattro Coupe	All	8013	
Avanti	Avanti II	All	2401	
BMW	1600, 2002	All	0155	
BMW	2800, Bavaria	All	0157	
BMW	318i	83-90	2006	
BMW	320i	All	0157	
BMW	325/318i(E36), 328	91-98	2008	
BMW	325e/es/l/is	84-90	2006	
BMW	528e	>7/85	2005	
BMW	528e	8/85-88	2006	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
BMW	528i, 530i	All	0157	
BMW	533i	All	2005	
BMW	535i, M535i, M5	>7/85	2005	
BMW	535i, M535i, M5	8/85-88	2006	
BMW	6 series	>82	0157	
BMW	6 series	83-86	2005	spacer is recommended for 85-6 635CSI
BMW	6 series	87	2006	
BMW	7 series	>86	0157	
BMW	7 series	87-93	2006	
BMW	850i	91>	2008	
BMW	M1	All	0157	
BMW	M3	86-90	2006	
BMW	M3	91-00	2008	
BMW	E36	ALL	2011	
BMW	E46 / NEW 3 SERIES	ALL	2012	
BMW	MINICOOPER	ALL	N/A	No Application.
Buick	All Models	>68	2700	
Buick	All Models	69>	2401	
Cadillac	All Models	>68	2700	
Cadillac	All Models	69>	2401	
Cadillac	All Models with tilt & telescopic column		2702	
Cadillac	Allante		2702	
Chevrolet	All Models	<68	2700	08.26.05 Discontinued NLA
Chevrolet	All Models, except below	69>	2401	08/04/05 Ignition must be on column for hub to work
Chevrolet	Astro	All	2401	
Chevrolet	Blazer	<92	2401	
Chevrolet	Blazer	93>	2401	
Chevrolet	Blazer S-10	<92	2401	
Chevrolet	Blazer S-10	93-97	2401	
Chevrolet	C/K Pickups	<92	2401	
Chevrolet	C/K Pickups	93-95	2401	
Chevrolet	Cavalier	82-94	2401	06/20/05 - 95 and later uses smaller upper shaft. MOMO hub too large.
Chevrolet	Corvette	69-83	2401	deletes use of telescopic column
Chevrolet	Corvette	84-93	2401	
Chevrolet	Corvette, tilt & telescopic column	84-93	2702	
Chevrolet	Nova	85-88	7711	
Chevrolet	Spectrum	All	4600	08.26.05 Discontinued NLA
Chevrolet	Suburban	All	2401	
Daihatsu	Charade	87>	3407	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Daihatsu	Feroza		3407	
Daihatsu	Rocky	>89	3405	
Daihatsu	Rocky	90>	3407	
Dodge	All Models	66-67	3601	08.26.05 Discontinued NLA
Dodge	Colt - GLI - Turbo	85-89	6101	
Dodge	Conquest		6101	
Dodge	Neon	94-	2401	09-08-04 SRT4 requires hub spacer for S/W clearance to turn signal stalk, custom wiring
Dodge	Stealth		6104	
Dodge	Viper		2401	
Dodge	PT Cruiser	2000>	2401	may require some modification to hub
Eagle	Summit	All	6101	
Ford	Aerostar	85>	4525	
Ford	All Models (except below)	68-71	4509	
Ford	All Models (except below)	72-82	4513	
Ford	Bronco 4 x 4	92	4513	
Ford	Bronco 4 x 4	93	4535	08.26.05 Discontinued
Ford	Bronco II	84-86	4525	
Ford	Escort	>83	4521	
Ford	Escort	84-90	4525	
Ford	Escort	91-03	4529	
Ford	EXP, EXP Turbo	84-90	4525	
Ford	Explorer		N/A	
Ford	F-150, F-250, F-350	>91	4513	
Ford	F-150, F-250, F-350	92-96	4535	08.26.05 Discontinued
Ford	Festiva		5702	
Ford	Focus	ALL	4538	
Ford	Mustang	65-73	4509	
Ford	Mustang	79-82	4513	
Ford	Mustang	84-02	4525	84-86 must purchase O.E. 87-89 Mustang cruise control switch assembly
Ford	Ranger	84-97	4525	Update 03/16/05
Ford	Taurus	>87	4525	
Ford	Tempo	84-94	4525	
Ford	Thunderbird	84-88	4525	84-88 must purchase O.E. 87-89 Mustang cruise control switch assembly
Ford	Probe	All	N/A	No Application.
Geo	Metro	>9/91	8907	
Geo	Metro	10/91-96	8911	
Geo	Prism		7711	
Geo	Tracker		8904	
GMC	Jimmy / Yukon	All	2401	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
GMC	S-15 / S-15 Jimmy	>92	2401	
GMC	Sonoma	93>	2401	
GMC	Suburban	All	2401	
GMC	Typhoon	All	2401	
Honda	Accord	83-8/89	4903	
Honda	Accord	94-95	7715	custom installation - needs washers to space out to nut
Honda	Accord	96-97	4920	
Honda	Accord with cruise control	>8/89	4904	
Honda	Accord	9/89-93	4909	
Honda	Accord	96-03	4917	Will not fit 94-95 Accord - shaft is too big
Honda	Civic	92-95	4911	
Honda	Civic	96-00	4920	Update 09-08-04
Honda	Civic with cruise control	>8/89	4904	
Honda	Civic with cruise control	9/89-92	4914	
Honda	Civic, Civic S	84-87	4903	
Honda	Civic, Civic S	88-91	4905	
Honda	Civic	01-05	4929	Update 09-08-04
Honda	CRX, CRX HF, CRX Si	84-87	4903	
Honda	CRX, CRX HF, CRX Si	88-91	4905	
Honda	Del Sol	ALL	4911	
Honda	Prelude	83-91	4903	
Honda	Prelude with cruise control	83-91	4914	
Honda	Prelude	92-03	N/A	No Application.
Honda	S2000	ALL	4920	Update 03/04/05
Hummer	Hummer	ALL	4513	Make sure the hub spline count is 40
Hyundai	Elantra		4703	
Hyundai	Excel, Pony	86-90	4701	
Hyundai	Scoupe, Excel	91-94	4703	
Hyundai	Tiburon	97>	4703	
Infinity	G20	93-98	3511	
Isuzu	Amigo		7903	
Isuzu	Rodeo		7903	
Isuzu	Trucks	89>	7903	
Jaguar	XJ6 (XJ40)	87-89	2202	
Jaguar	XJ6 (XJ40)	90-94	2207	
Jaguar	XJ6, XJ12	75-86	2201	
Jaguar	XJS	76-89	2201	
Jaguar	XJS	90-95	2208	08.27.05 Discontinued
Jeep	Cherokee	>83	2401	



Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Jeep	Cherokee	84>	2401	
Jeep	CJ 5/6/7, Renegade, Wrangler		2401	
KIA	Sportage		5702	
Lincoln	Continental	All	4513	
Lincoln	Continental MK VII	All	4525	
Mazda	323	88>	5702	spacer may be needed for 88 and later models
Mazda	626	7/80-91	5702	spacer may be needed for 88 and later models
Mazda	626	7/80-91	5712	
Mazda	929	>91	5702	
Mazda	B2000 Sundowner	All	5702	
Mazda	GLC	7/80-85	5702	
Mazda	Miata	89-02	5702	07/16/04 - customer called and said horn is not attaching correctly on 02 model.
Mazda	MPV		5702	
Mazda	MX6	ALL	N/A	No Application.
Mazda	RX-7	7/80-85	5702	
Mazda	RX-7, RX-7 Turbo	86-02	5705	
Mercedes Benz	(W107)	>85	6002	
Mercedes Benz	(W113) 230, 250, 280SL	65-70	6000	
Mercedes Benz	(W114) 300D, 280C, 250	68-76	6001	
Mercedes Benz	(W115) 200, 220, 220D, 230, 240D, 380, 560SL/SLC	68-76	6001	
Mercedes Benz	(W115) 200, 220, 220D, 230, 240D, 380, 560SL/SLC	80>	6004	
Mercedes Benz	(W116) 280S, 450SE/SEL, 450SEL 6.9, 300 SD	73-80	6001	
Mercedes Benz	(W123) 280E/CE, 300D/CD, 240D, 300SD, 300TD	77-83	6004	
Mercedes Benz	(W124) 300E/D	86-93	6004	
Mercedes Benz	(W126) 300SD, 380SE/SEL, 500, 560 SE/SEL	81-91	6004	
Mercedes Benz	(W126C) 380SE, 500 SEC	81-92	6004	
Mercedes Benz	(W129)		6004	
Mercedes Benz	(W140)		6004	
Mercedes Benz	(W201) 190E, 190D, 190 2.3 16V	84-93	6004	
Mercedes Benz	C230	01-03	2048	
Mercury	All Models	72-80	4513	
Mercury	Capri	84-87	4525	
Mercury	Cougar	84-89	4525	
Mercury	LN-7	84>	4525	
Mercury	Lynx	84>	4525	
Mercury	Sable	86-87	4525	
Mercury	Topaz	84-94	4525	
Mercury	Tracer	88	5702	
Mistubishi	Colt	85-88	6101	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Mistubishi	Colt	89-91	6105	
Mistubishi	Eclipse	90-03	6101	
Mistubishi	Galant	86-87	6101	
Mistubishi	Galant	88-92	6104	
Mistubishi	Galant	93-98	6109	08.26.05 Discontinued NLA
Mistubishi	Lancer	>88	6101	
Mistubishi	Lancer	89-91	6105	
Mistubishi	Lancer	92-94	6106	
Mistubishi	Mirage	>91	6101	
Mistubishi	Mirage	92>	6106	
Mistubishi	GT3000	All	6104	
Mistubishi	Montero	>91	6101	
Mistubishi	Montero	92>	6106	
Mistubishi	Pickup	82-89	6101	
Mistubishi	Pickup	90>	6104	
Mistubishi	Tredia, Cordia, Starion	All	6101	
Mistubishi	Van		6101	
Nissan	Altima	ALL	N/A	no application.
Nissan	200SX	77-79	3502	
Nissan	200SX, 200SX Turbo	84-02	3507	
Nissan	240, 260, 280-Z, 280ZX	All	3503	
Nissan	240SX	89-97	3508	will not fit Hicas equipped models, S13 cars with cruise use 3507
Nissan	300ZX	>88	3507	
Nissan	300ZX Non Turbo	89>	3508	
Nissan	510, 610	All	3503	
Nissan	810	All	3503	
Nissan	910, Maxima	83-84	3506	
Nissan	Axxes	89>	3507	
Nissan	Hardbody	All	3507	
Nissan	Maxima	85-88	3507	
Nissan	Maxima	89-98	3508	
Nissan	NX 1600 / 2000	91-93	3511	
Nissan	Pathfinder	>93	3507	
Nissan	Pathfinder	94>	3512	
Nissan	Pulsar	87-90	3508	
Nissan	Pulsar NX	83-86	3507	
Nissan	Sentra	>82	3506	
Nissan	Sentra	83-90	3507	
Nissan	Sentra	91-03	3514	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Nissan	Stanza	85-86	3506	
Nissan	Stanza	87-90	3507	
Nissan	Trucks	>86	3503	
Oldsmobile	All Models	69>	2401	
Plymouth	Colt	85-88	6101	
Plymouth	Colt	89-91	6105	
Plymouth	Colt	92-93	6106	
Plymouth	Conquest	84>	6101	
Plymouth	Lazer	89>	6101	
Pontiac	All Models	69>	2401	
Pontiac	Fiero	All	2401	
Porsche	356B, 456C	58-65	0230	
Porsche	911	7/74	0230	Fits 912 also
Porsche	911, 911 Carrera, 930 Turbo	8/74-03	L231	
Porsche	914/4	>71	8000	08.26.05 Discontinued NLA
Porsche	914/4	72-76	8002	
Porsche	914/6	>71	0230	
Porsche	924, 924 Turbo	>82	8010	
Porsche	928, 928S, 928 S4	78-92	7005	
Porsche	944	83-85	8010	
Porsche	944	85 1/2>	7004	
Porsche	944 Turbo	86-89	7004	
Porsche	964	91-94	7004	
Porsche	Boxster	97-04	7004	column not threaded deep enough, requires a spacer for nut to tighten to
Porsche	Carrera 2, Carrera 4, RS	89-94	7004	
Rover	Range Rover	87>	5607	
Rover	Range Rover 4 x 4	>86	5601	to be discontinued
Subaru	Hardtop, Sedan DL	80-84	7302	
Subaru	Hatchback 4WD GL	80-84	7302	
Subaru	Impreza		7306	
Subaru	Legacy 1.8 - 2.0		7306	
Subaru	Station Wagon 2WD, 4WD, Brat	80-84	7302	
Suzuki	Samurai 4 x 4	All	8904	
Suzuki	Sidekick	>92	8904	
Suzuki	Sidekick	93>	8912	
Suzuki	Swift	89-91	8907	
Suzuki	Swift	92>	8911	
Suzuki	Vitara	93-96	8912	
Toyota	4 Runner	>89	7711	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Toyota	4 Runner	90-96	7715	
Toyota	Camry	>86	7711	
Toyota	Camry	87-90	7715	
Toyota	Celica	82-85	7711	
Toyota	Celica	94-02	7730	
Toyota	Celica FWD 16 valve	86-93	7715	
Toyota	Corolla	84-88	7711	
Toyota	Corolla (All Models)	89>	7715	
Toyota	Corolla Twin Cam / 16v FWD	85-88	7713	
Toyota	Cressida	83-92	7711	
Toyota	FX16	>87	7713	
Toyota	Landcruiser	85-90	7713	
Toyota	Landcruiser	91-96	7715	
Toyota	Landcruiser 4 x 4, SW	83-84	7712	
Toyota	Minivan	83-89	7711	
Toyota	MR2	85-89	7714	
Toyota	MR2	90-91	7715	
Toyota	MR2	92-95	7728	
Toyota	Toyota		7730	
Toyota	Paseo	92-97	7715	
Toyota	Pickup Trucks, 4WD	85-87	7711	
Toyota	Pickup Trucks, 4WD	87-96	7715	
Toyota	RAV 4		7730	
Toyota	Starlet	86>	7714	
Toyota	Supra	82-85	7711	
Toyota	Supra	86-93	7713	
Toyota	Supra	94-98	7728	
Toyota	Tercel	83-89	7713	
Toyota	Tercel	90-98	7715	
Toyota	Tercel, 4WD	82	7711	
Volkswagen	Beetle	>6/74	0248	
Volkswagen	Beetle	6/74>	8010	
Volkswagen	Beetle	98-on	8015	
Volkswagen	Corrado	89-95	8014	
Volkswagen	Dasher	78>	8010	
Volkswagen	Fox	88-91	8010	
Volkswagen	Golf, Golf GTI, GTI 16v	85-88	8010	
Volkswagen	Golf, Golf GTI, GTI 16v	89-98	8014	
Volkswagen	Jetta, Golf	99-02	8015	

Hub Application Guide

Hubs for vehicles with airbags to be used for racing purposes only!
 May lose horn and/or cruise control function

Make (select)	Models	Year	Part #	Notes
Volkswagen	Jetta, Jetta GLI	>88	8010	
Volkswagen	Jetta, Jetta GLI	89-98	8014	
Volkswagen	Karmann Ghia	>6/74	0248	
Volkswagen	Karmann Ghia	7/74>	8010	
Volkswagen	Passat	90-96	8014	
Volkswagen	Quantum, Quantum Syncro	All	8010	
Volkswagen	Rabbit, Rabbit GTI	78-84	8010	
Volkswagen	Scirocco, Scirocco 16v	78-88	8010	
Volkswagen	Vanagon	All	8012	
Volvo	240 Series	82>	9010	
Volvo	480 Series	88>	9016	
Volvo	740 Series	84>	9011	
Volvo	740 Series	90>	9018	
Volvo	760 Series	83>	9011	
Volvo	780 Series	90>	9018	
Volvo	850, 960		9018	
Volvo	940		9011	
Yugo	GV	85>	4014	to be discontinued

g for horn

